

Menu


HISTORY FILE MAP for year 2002

REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK



354.14:31-17:07: 2h 21m 2048bps, 16m 512bps RT data, and 3h 40m 512bps PB (354.10:51-14:31) data lost due to snow at Goldstone DSS-25. Receivers unable to obtain lock. DR G102074 refers.